

# 2006 PACIFIC AVIATION DIRECTORS WORKSHOP

# Present Situation in The State of Yap

# Yap International Airport

Problems and Challenges

Taxiway and Apron

Fuel Line

Schedule Change

# The Airports

Yap International Airport



Falalop Ulithi Runway





Fais Runway



Falalop Woteai Runway

# On-Going AIP Projects Status

- Typhoon Damaged Restoration
- ARFF 1500 gallon Two Vehicles
- ARFF Building Construction
- Terminal Apron & Airfield Signage Rehab
- Runway Sweeper
- Airport Master Plan

# Typhoon Damage Restorations

- Terminal Building Rehab
- Lighting and Signage Upgrade
- Perimeter Fencing
- Apron Quick Fix







March 10, 2006



March 10, 2006

# Lighting and Signage



# Fencing



## ■Future and Pending Projects

Runway Resurfacing  
Runway Shoulder & Lighting  
Runway End Turn-around  
Maintenance Building  
Water Rescue & EMS Equipment  
Safety zone Improvement  
Access Roads  
Safety Area Stabilization  
Clearing of Mound & Fill of Depressed Areas  
Cargo Terminal  
Runway Extension  
Terminal Expansion  
Parking Expansion  
Apron Expansion  
Fuel Facility



THANK YOU!